

Dalham Parish Council

Annual Inspection of Council Property 2025

DRAFT COPY

| Ref no. | Item | Photograph | Location | | Condition | Action required |
|---------|-------------------------------------|---|---|-------------------------------|---|---|
| | | | Address | What3words | | |
| 1 | Kissing gate |  | Bottom of Chestnut Avenue off Gazeley Rd | evaporate.lorry.trickles | ACCEPTABLE | None |
| 2 | Recycled plastic seat |  | Current location: Chapelfield Barn, The Street | broadcast.snippet.enigma | BRAND NEW, YET TO BE INSTALLED | To be installed |
| 3 | Metal seat |  | The Street, Dalham to the right of the walks notice board | chief.gossiping.strongly | GOOD | None |
| 4 | Village sign |  | Junction of Stores Hill and the Street | rifled.panoramic.irrigated | GOOD | None |
| 5 | Walks notice board and footpath map |  | The Street, Dalham | chief.gossiping.strongly | GOOD | None |
| 6 | York stone plaque |  | Set into paving outside front door of the village hall | live.prune.inhaled | GOOD | None |
| 7 | Parish Council notice board |  | The Street, Dalham | plums.scavenger.verbs | GOOD | Glass needs cleaning |
| 8 | Parish Council notice board |  | Dunstall Green and the corner of Seven Elms Lane | corrects.domestic.couple r | GOOD | None |
| 9 | QR Code signs |  | Various locations | Various locations | GOOD | None |
| 10 | Circular Walk markers | | Various locations | Various locations | GOOD | None |
| 11 | Grit bin 1 |  | Corner of Stores Hill and Dalham Road | warbler.inflating.nuggets | GOOD | None |
| | Grit bin 2 | | Corner of Denham Road and The Street | galaxy.built.submitted | GOOD | |
| | Grit bin 3 | | Corner of Denham Road and Dunstall Green Road | lined.finalists.pedicure | GOOD | |
| 12 | Defibrillator |  | Dalham Village Hall | shout.volcano.bulge | Good, but pads will need replacing in October 2025; battery OK but past replacement date | Replace pads later in 2025; battery in 2026? |
| 13 | Lectern board |  | Malt Kiln | ounce.organist.vanished | GOOD | None |
| 14 | Ice warning sign |  | Denham Road at top of hill | slack.elect.sitting | GOOD | None |
| 15 | VAS and brackets |  | Various locations | Various locations | VAS fine but batteries nearing end of life Posts are fine except for the one opposite the Village Hall Brackets all fine. | Replace batteries. Stake post opposite Village Hall to make it stand more vertically |

Inspection carried out by:

Date:

Signed: